	09/11/2011	2 pages
P	Campaign	
IKET-015	Type: Customer Satisfaction Campaign Area of Application: Europe Subject: LAND CRUISER12# / HILUX- 1KD Engine Oil Strainer clogging Models: HILUX; LAND CRUISER Model codes: KUN26; KUN36; KUN51; KUN61; KDJ120; KDJ125	Engine

## WHAT IS TOYOTA GOING TO DO?

Owners of the involved vehicles will receive a campaign notification by first class mail. TOYOTA retailers / authorized repairers will exchange the injection nozzle seats by new ones.

## WHICH VEHICLES ARE INVOLVED?

Model Name	Model Code	VIN Range			Production
		WMI	VDS	VIS	Period
LAND CRUISER 120	KDJ120	JTE	BZ29J#	00049705 - 00160767	June,2004 Through October,2007
	KDJ125	JTE	AZ29J#	00019035 - 00050831	
HILUX	KUN26	AHT	FZ29G#	#9002934 - #9022470	October,2006 Through April, 2008
	KUN26	MR0	FZ29G#	01541975 - 01710550	
	KUN36	AHT	CZ39G#	05004258 - 05005235	
	KUN36	AHT	EZ39G#	07005011 - 07006639	
	KUN51	AHT	YZ59G#	08002450 - 08002450	
	KUN61	AHT	ZZ69G#	05001632 - 05002851	

Note : # indicates that various characters may occupy that position. IMPORTANT :

- Not all vehicles in these ranges are affected and/or sold in your country
- The detailed VIN-list of affected vehicles is available at your local TOYOTA retailers / authorised repairers



TOYOTA MOTOR EUROPE NV/SA

## WHAT SHOULD AN OWNER DO IF THEY ARE CONCERNED ABOUT THIS CONDITION?

- Owners are requested to contact their local TOYOTA retailer / authorized repairer for confirmation whether their vehicle is involved.
- Owners are requested to contact their local TOYOTA retailer / authorized repairer for diagnosis and repair.
- This Customer Satisfaction Campaign will be performed at no cost by any TOYOTA retailer / authorized repairer

## WHEN WILL THIS CAMPAIGN EXPIRE?

This Customer Satisfaction Campaign will be available at NO COST to the vehicle owners until the end of 08/2014.

