



Recall / Special Service Campaign

Section : Chassis

C/I Ref. No. : 5KGM-208

Issue Date : 16 May 2005

Page : 1 of 2

Area Application: Toyota Motor Europe Operational Area

Model Name: Land Cruiser 9#, 4Runner, Tacoma, Sequoia, Tundra

Model Code: LJ90, VZJ90, KDJ90, LJ95, RZJ95, VZJ95, KZJ95, KDJ95, VZN180, VZN185, VZN170, UCK45, VCK40, UCK40

Campaign Type: Recall / Special Service Campaign

Subject: Front Suspension Lower Ball Joint

WHAT IS TOYOTA GOING TO DO?

Owners of the involved vehicles will receive a campaign notification by first class mail. Toyota retailers / authorized repairers will replace the Front Suspension Lower Ball Joint.

WHICH VEHICLES ARE INVOLVED?

Vehicle Model	Model Code	Vehicle Identification Number (VIN)			Production Period
		WMI	VDS	VIS	
Land Cruiser 9#	LJ90	JTE	AE91J#	00003050 -00003127	December 25, 2001 through June 26, 2002
	VZJ90		AN99J#	00005399 - 00005647	June 22, 2001 through June 26,2002
	KDJ90		AZ99J#	00008715 - 00012558	May22, 2001 through January 7, 2002
	LJ95		BE91J#	00011840 - 00014521	May 25, 2001 through June 26, 2002
	RZJ95		BM99J#	00054512 - 00049117	June 29, 2001 through March 5, 2002
	VZJ95		BN99J#	00086207 - 00103248	May 22, 2001 through July 31, 2002
	KZJ95		BY99J#	00165956 - 00170728	June 11, 2001 through April 24, 2002
	KDJ95		BZ99J#	00018273 - 00036640	May 22, 2001 through August 9, 2002
4Runner	VZN180	JT3	GN86R#	#0216936 - #0258908	June 22, 2001 through August 3, 2002
	VZN185		HN86R#	#0356664 - #0390208	May 22, 2001 through July 26, 2002
			HN87R#	20372962 - 2378964	November 28, 2001 through January 25, 2002
Tacoma	VZN170	5TE	HN72N#	#Z195806 - #Z352476	January 2, 2003 through December 15, 2003
			WN72N#	#Z045150 - #Z352979	February 1, 2002 trough December 16, 2003
Sequoia	UCK45	5TD	BT44A#	#S090606 - #S205681	January 21, 2002 through August 22, 2003
			BT48A#	#S099354 - #S205646	March 5, 2002 through August 22, 2003
Tundra	VCK40	5TB	BN441#	3S391434 - 3S422120	February 24, 2003 through June 5, 2003
	UCK40		BT481#	3S384986 - 3S430466	February 4, 2003 through July 2, 2003

Note: # indicates that various characters may occupy that position.

IMPORTANT: - Not all vehicles in these ranges are affected and/or sold in your country.
- The detailed VIN-list of affected vehicles is available at your local Toyota retailers / authorized repairers.

TOYOTA

TOYOTA MOTOR EUROPE NV/SA



Recall / Special Service Campaign

Section : Chassis

C/I Ref. No. : 5KGM-208

Issue Date : 16 May 2005

Page : 2 of 2

WHAT SHOULD AN OWNER DO IF THEY ARE CONCERNED ABOUT THIS CONDITION?

- Owners are requested to contact their local Toyota retailer / authorized repairer for confirmation whether their vehicle is involved.
- Owners are requested to contact their local Toyota retailer / authorized repairer for repair.
- This Recall / Special Service Campaign will be performed at **NO COST** by any Toyota retailer / authorized repairer.

WHEN WILL THIS RECALL / SPECIAL SERVICE CAMPAIGN EXPIRE?

This Recall / Special Service Campaign will be available at **NO COST** to the vehicle owners without time limitation.