



TOYOTA

ALWAYS A
BETTER WAY

AYGO

Side sills 5-door

Installation Instructions

Model year: 2014/05, 2018/05

Vehicle code: KGB40*-A***KW



Part number: PZ415-90492-00
PZ415-90492-BA
PZ415-90492-DF
PZ415-90492-HU
PZ415-90492-MG
PW156-0H000-EG
Adhesion promoter (2x)

Manual reference number: AIM 003 127-4

Revision record

Rev. No.	Date	Page	Picture	Update	New	Deleted steps
1	12-05-14	3/6/8	Tools/8	X		
	12-05-14	6	7			7
2	08-01-18	All	All		Temperature checks	
3	19-12-18	1, 2		Vehicle code	Part No.	
Rev. No.	Date	Page	Steps	Remarks		
△ ₄	15/01/2019	2		Adhesion Promoter Qty 4 to 2		

PZ415-90492-00, PZ415-90492-BA, PZ415-90492-DF, PZ415-90492-HU, PZ415-90492-MG, PW156-0H000-EG



		3M			
		adhesion promoter PZ415-00000-00 △ ₄ 2x	+ °C	? °C	DEGREASER CLEANER AIM 003-516-*





INFO




Material Safety Data Sheet




Technical Data Sheet








<p>1</p>	<p>< 20°C → 2</p> <p>20°C - 40°C → 3</p>	<p>2</p>
<p>3</p>	<p>20°C - 40°C → 3</p>	<p>INFO</p>


2




<p>1</p>	<p>< 20°C → 2</p> <p>20°C - 40°C → 4</p>	<p>2</p>
<p>3</p>	<p>20°C - 40°C → 4</p>	<p>INFO</p>

3










7





8












RHS = LHS



14

INFO





TOYOTA

CHECK SHEET



TOYOTA





Model / Year

**Aygo - 5 Door
2014/05, 2018/05**

Side sills

VIN n°

ALWAYS A
BETTER WAY



Installation Date:

.. / .. / ..

Technician Name & Signature:

Stamp: