

GTS V17.2 Version Up Information				
Category	Vehicle	System	Function	Content
Vehicle Coverage	-	-	-	Covered all the models by October 2022
New Functions	FC SYSTEM	EV	Predictive Detection Related Information Reset	Added new Utility "Predictive Detection Related Information Reset". Description: This function is used to reset the Predictive Detection Related Information.
New Functions	FC SYSTEM	EV	FC Stack Coolant Air Bleeding	Added new Utility "FC Stack Coolant Air Bleeding". Description: This function is used to bleed the air from the FC stack coolant.
New Functions	TUNDRA HEV	Transmission	SLU Compensation Code Reset	Added new Utility "SLU Compensation Code Reset". Description: This function is used to reset the SLU Compensation Code.
New Functions	RX350h RX500h RX450h+	Engine	PM Deposition Lv. MID Display Frequency Setting	Added new Utility "PM Deposition Lv. MID Display Frequency Setting". Description: This function is used to set the GPF PM Deposition Level MID Display Frequency Mode.
New Functions	ES250/ES260	Engine	Total Short Trip Estimate Reset	Added new Utility "Total Short Trip Estimate Reset". Description: This function is used to reset the Total Short Trip Estimate of GPF Catalyst.
New Functions	ES250/ES260	Engine	Total Short Trip Estimate Registration	Added new Utility "Total Short Trip Estimate Registration". Description: This function is used for Total Short Trip Estimate Registration of GPF Catalyst.
New Functions	SIENNA HV	Interface Box	ADK Key Number Read	Added new Utility "ADK Key Number Read". Description: To get the update information of ADK Security Key.
New Functions	SIENNA HV	Interface Box	ADK Security Key Update	Added new Utility "ADK Security Key". Description: To update ADK Security Key.
New Functions	NX350 NX350h NX450h+	Passenger Seat	Customize Setting Initialization	Added new Utility "Customize Setting Initialization". Description: This function is used to initialize simultaneously all customize settings for the functions controlled by the ECU.
New Functions	NX350 NX350h NX450h+	Passenger Seat	Seat Position Memory Clear	Added new Utility "Seat Position Memory Clear". Description: This function is used to clear the memory information of the seat position.
New Functions	NX350 NX350h NX450h+	Passenger Seat	Seat Position/Endpoint Information Clear	Added new Utility "Seat Position/Endpoint Information Clear". Description: This function is used to clear the memory information of the seat position and the initialization information of the endpoint.
Functional Improvement	-	-	Vehicle Connect	Modified it not to display the announce screen for changing to a cable of the vehicle interface modules for Ethernet communication (S301-34 screen), when selected the Ethernet vehicle and there is not the installation of the Ethernet system.
Functional Improvement	-	Clearance Warning	ECU Calibration	Added text to the screen that appears when sensor registration fails, instructing the user on the next action to take.
Functional Improvement	-	Clearance Sonar	Clearance Sonar Detection/Steering Adjustment	Added text to the screen that appears when clearance sonar detection area adjustment fails, instructing the user on the next action to take.
Functional Improvement	bZ4X	Front Radar Sensor	Forced Heater Activation	Added new Utility "Forced Heater Activation". Description: This function is used to force the activation of the Front Radar heater.
Functional Improvement	With digital key	Entry&Start	Digital Key Serial Number Transmit	Change to non-display. (A vehicle works automatically without using GTS.)
Functional Improvement	-	Engine Transmission	PM Regenerate Mode	Added the screen to promote attention to FF1M-HEV model.
Functional Improvement	bZ4X	Brake/EPB	Brake System Air Bleeding	revised the number of times Brake System Air Bleeding.
Functional Improvement	86	Active Sound Control	Customize	Modified the displayed on the following Customize Function - "Others"->"Active Sound Control"
Functional Improvement	-	MainBody	ActiveTest	Change "Low Beam Headlight" to non-display.
Bug Fix	SEQUOIA HEV	Circumference Monitoring Camera Control Module	Vehicle Information Registration	Fixed a problem with incorrect screen icons display within the Utility. *Screen icon「?」→「i」
Bug Fix	TUNDRA	Cruise Control	DTC	Fixed the bug; Solved the problem that the DTC data items not displayed correctly. *「Lost Communication with Trailer Brake Control Module」
Bug Fix	HIGHLANDER	Four Wheel Drive	Data List	Fixed the bug; Solved the problem that the Data List not displayed correctly. *「Front Position Sensor Stuck OFF Abnormal Count」 *「Front Position Sensor Stuck OFF Abnormal Count History」 *「Front Position Sensor Stuck ON Abnormal Count」 *「Front Position Sensor Stuck ON Abnormal Count History」 *「Retry Coupling Connect Count History when Stuck ON Interim Malfunction」
Bug Fix	LS500h	EMPS	Vehicle Connect	Fixed the bug; Solved the problem that there are cases that the vehicle is not identified automatically.
Bug Fix	COROLLA CROSS HV	Power Distribution Box	Vehicle Connect	Fixed the bug; Solved the problem that there are cases that the vehicle is not identified automatically.
Bug Fix	UX250h	Adaptive Variable Suspension System	Vehicle Connect	Fixed the bug; Solved the problem that there are cases that the vehicle is not identified automatically.
Bug Fix	SIENTA	RR Door/RH PSD	Vehicle Connect	Fixed the bug; Solved the problem that there are cases that the vehicle is not identified automatically.
Bug Fix	SIENTA	RL Door/LH PSD	Vehicle Connect	Fixed the bug; Solved the problem that there are cases that the vehicle is not identified automatically.