

Proace Multimedia overview

Type of unit	Firmware version	Firmware URL	License	Map version	Map URL
NAC Wave 1	From TD1 page Latest version: 7.3.1	https://d24bc9lyrt5en5.cloudfront.net/psa/firmware/firmware_master.zip	From TD1 Together with FW update	Latest version: 12.0.0	https://d24bc9lyrt5en5.cloudfront.net/psa/map/wave1/Map update 12.0.0/PSA_map-eur_12.0.0-NAC_EUR_WAVE1.tar
NAC Wave 2	From “ Support PPT” file From TD1 once page was reviewed (est. June) Latest version: 21.07.16.32_NAC-r0	https://d24bc9lyrt5en5.cloudfront.net/psa/firmware/wave2/21.07.16.32_NAC-r0/PSA_ovip-int-firmware-version_21-07-16-32_NAC-r0_NAC_EUR_WAVE2.tar	Over the air From TD1 once page was reviewed (est. June)	Latest version: 10.0.0-r0	https://d24bc9lyrt5en5.cloudfront.net/psa/map/wave2/Map update 10.0.0-r0/PSA_map-eur_10.0.0-r0-NAC_EUR_WAVE2.tar
Units without GPS navigation capabilities					
RCC Continental	From TD1 page Latest version: 7.3.1	https://d24bc9lyrt5en5.cloudfront.net/psa/firmware/firmware_master.zip	From TD1 Together with FW update	Not applicable	
RCC Bosch	From “ Support PPT” file From TD1 once page was reviewed (est. June) Latest version: 1_074_16.1B116	https://d24bc9lyrt5en5.cloudfront.net/psa/firmware/rcc/1_074_16.1B116/SRMTMJBPUTOBACK.20171130101445.tar	Via Service Now flow, manual request.	Not applicable	
RD6 radio - Clarion	All updates are delivered via Diagbox as ECU reflash format.				