

 TOYOTA	<h1>Campaign</h1>	
	Type: Customer Satisfaction Campaign Area of Application: Europe Subject: Suction Control Valve Models: LAND CRUISER Model codes: KDJ150; KDJ155	Engine
4KET-1422		

WHAT IS TOYOTA GOING TO DO?

Owners of the involved vehicles will receive a campaign notification by first class mail. TOYOTA retailers / authorized repairers will check and replace the Suction Control Valve.

WHICH VEHICLES ARE INVOLVED?

Model Name	Model Code	WMI	VIN range		Production Period
			VDS	VIS	
LAND CRUISER 150 (PRADO)	KDJ150	JTE	BH3FJ#	0K147088-0K151550	September 17th 2014 through November 10th, 2014
				05085004-05087550	
			BH8FJ#	0K147331-0K148752	
	05085592-05085592				
	KDJ155	RUT	BH9FJ#	0K148213-0K148213	
	KDJ150		CH3FJ#	05011229-05011397	
		BH8FJ#	F0018775-F0019628		

Note : # indicates that various characters may occupy that position.

IMPORTANT :

- Not all vehicles in these ranges are affected and/or sold in your country
- The detailed VIN-list of affected vehicles is available at your local Toyota retailers / authorised repairers

WHAT SHOULD AN OWNER DO IF THEY ARE CONCERNED ABOUT THIS CONDITION?

- Owners are requested to contact their local TOYOTA retailer / authorized repairer for confirmation whether their vehicle is involved.
- Owners are requested to contact their local TOYOTA retailer / authorized repairer for diagnosis and repair.
- This Customer Satisfaction Campaign will be performed at no cost by any TOYOTA retailer / authorized repairer

WHEN WILL THIS CAMPAIGN EXPIRE?

This Customer Satisfaction Campaign will be available at NO COST to the vehicle owners until the end of 12/2017 .