



Highlander

Body Side Mouldings

Installation instructions

Model year: 2010





Vehicle code: GSU45* - BRA*KX





Part number: PT29A-48080-XX


Manual reference number: AIM 002 245-0

Revision Record


Rev. No.	Date	Page	Picture	Update	New	Deleted

	A  1x		
	B  1x		
	C  1x		
	D  1x		
	 ± 300 mm		 Cleaner







5





6





7




8





9



10



11



12