



Recall / Special Service Campaign

Section : Brake
C/I Ref. No. : 8K3E-333
Issue Date : 18 Jul 2008
Page : 1 of 1

Area Application: Toyota Motor Europe Operational Area

Model Name: TSAM Corolla

Model Code: ZZE150, ZRE151, NDE150, ADE150

Campaign Type: Recall / Special Service Campaign

Subject: Rear Brake Caliper Concern

WHAT IS TOYOTA GOING TO DO?

Owners of the involved vehicles will receive a campaign notification by first class mail. Toyota retailers / authorized repairers will re-tighten both caliper attaching bolts from the left and right rear brake caliper.

WHICH VEHICLES ARE INVOLVED?

Vehicle Model	Model Code	Vehicle Identification Number (VIN) Range			Production Period
		WMI	VDS	VIS	
Corolla TSAM	ZZE150	AHT	LA5#E#	03006397 - 03012306	Jan. 18, 2008 through May 12, 2008
	ZRE151		LB5#E#	03009636 - 03017221	
			LB58E4	83008961	
			LB58E5	83009472	
	NDE150		LD5#E#	03000671 - 03003539	
	ADE150		LE56E#	03002170 - 03002726	
			LF56E#	03002317 - 03002926	

Note: # indicates that various characters may occupy that position.

IMPORTANT: - Not all vehicles in these ranges are affected and/or sold in your country.
- The detailed VIN-list of affected vehicles is available at your local Toyota retailers / authorized repairers.

WHAT SHOULD AN OWNER DO IF THEY ARE CONCERNED ABOUT THIS CONDITION?

- Owners are requested to contact their local Toyota retailer / authorized repairer for confirmation whether their vehicle is involved.
- Owners are requested to contact their local Toyota retailer / authorized repairer for repair.
- This Recall / Special Service Campaign will be performed at **NO COST** by any Toyota retailer / authorized repairer

WHEN WILL THIS RECALL / SPECIAL SERVICE CAMPAIGN EXPIRE?

This Recall / Special Service Campaign will be available at **NO COST** to the vehicle owners without time limitation.

