



TOYOTA

ALWAYS A
BETTER WAY

Corolla (HB)

Rear bumper protection plate

Installation Instruction

Model year: 2019/01

Vehicle code: **E*1**-DH****



Part number: PW178-02006

Manual reference number: AIM 004 340 - 2

Revision Record


Rev. No.	Date	Page	Picture	Update	New	Deleted steps
1	18.10.18	6, 7	8, 9, 11	X		
2	04.12.18	2, 3, 4, 5, 6, 7	3, 5, 7, 9, 10, 11, 12, 13	X		

PW178-02006











Material Safety Data Sheet




Technical Data Sheet




1





2




3






4




5




<p>1</p>	<p>< 20°C → 2</p> <p>20°C - 40°C → 7</p>	<p>2</p>
<p>3</p>	<p>20°C - 40°C → 7</p>	<p>INFO</p> <p>6 → 12</p>

6




<p>1</p>	<p>< 20°C → 2</p> <p>20°C - 40°C → 8</p>	<p>2</p>
<p>3</p>	<p>20°C - 40°C → 8</p>	<p>INFO</p> <p>7 → 12</p>



7




8




9




10




11



12






13




14

INFO



> 0,5 meter



CHECK SHEET



TOYOTA





Model / Year

**Corolla (HB)
2019/01**

**Rear Bumper
Protection Plate**

ALWAYS A
BETTER WAY

VIN n°



Installation Date:
... / ... / ...

Technician Name & Signature:

Stamp: